

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1302
ENE
> 1
1.665 mi.
8793 ft.

VAULT 2889
OCEAN AVE & AVE Z
BROOKLYN, NY

NY Spills S106011956
N/A

Relative:
Higher

Actual:
11 ft.

SPILLS:

Name: VAULT 2889
Address: OCEAN AVE & AVE Z
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0211981 / 2003-09-26
Facility ID: 0211981
Facility Type: ER
DER Facility ID: 196478
Site ID: 238683
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2003-03-05
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 2003-03-05
CID: 205
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-03-05
Spill Record Last Update: 2003-09-29
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 001
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed e2mis #147399: 3-5-03 1040 HRS S. FULLER # 37342 SPLICER I&A NETWORK REPORTS WHILE INSPECTING STRUCTURE (WAS SENT THERE FOR A SMOKING TRANSF) VS2889 W/S OCEAN AVE 25' S/O AVE Z HE FOUND APPROX 1 QUART UNKNOWN OIL ON 150 GALLONS WATER. THIS TRANSF IS ON FDR. 10B68 AND FEEDER IS OFF THE SYSTEM FOR SCHEDULE WORK. HISTORICAL RECORD OF TRANSF IS 12PPM AND WAS LAST TESTED 11-30-95. UNIT WAS PRESSURE TESTED AND IT TESTED GOOD (HELD PRESSURE) UNIT WAS NOT BELOW MIN. AS PER MR. FULLER THIS UNIT IS TO BE REPLACED DUE TO DEF NETWORK HOUSING. TO BE LEC IN LINE MANHOLE OR REPLACE ON OUTAGE. HE DOES NOT SEE A SEWER CONNECTION OR SUMP AT THIS TIME. HE TOOK (2) SAMPLES, ONE FROM THE STRUCTURE AND ONE FROM THE TRANSF SO THAT THE UNIT CAN BE DRAINED WHEN REMOVED FROM STRUCTURE. HE REQUESTED EMERG PRIORITY FOR PCB SAMPLE RESULT. CLEANUP PENDING SAMPLE RESULT. PLACED E.S.TAG # 39182. UPDATE 3-5-03 2045 HRS CHEM LAB # 03-01819-001 SAMPLE FROM STRUCTURE 13 PPM SAMPLE FROM TRANSF 03-01819-002 15 PPM LAZ # 04425 3/11/03 01:10 HRS. -- FEEDER CONTROL REP H.TATE REQUESTED CLEANUP OF VAULT DUE TO UNDERGROUND CREW ON LOCATION TO PLACE LIVE-END CAP IN VAULT. NOTIFIED C.FERNANDEZ, O.S. BROOKLYN ENV. OPS. ASSIGNED ENV OPS CREW MIDDLETON & GLODOWSKI TO DO INITIAL CLEANUP AND LEAVE TAG IN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PLACE PENDING TRANSFORMER REPLACEMENT AND FINAL CLEANUP. -- W.W. #17344 -- UPDATE 3/11/03 03:55 HRS. -- A. GLODOWSKI OF BROOKLYN ENV. OPS. REPORTS HE AND J.MIDDLETON COMPLETED INITIAL CLEANUP -- DOUBLE-WASHED STRUCTURE WITH BIOGEN 760 AND REMOVED DEBRIS & LIQUID WITH VACTOR #60722. SUMP IS PARTIALLY CEMENTED; UNABLE TO COMPLETELY CEMENT IT BECAUSE STRUCTURE IS MAKING WATER THROUGH THE SUMP. ENV. STOP TAG WAS LEFT IN PLACE PENDING TRANSFORMER REMOVAL. FEEDER CONTROL REP. H. TATE NOTIFIED THAT STRUCTURE IS READY FOR UNDERGROUND TO WORK. -- W.W. #17344 -- 3/18/03 11:30 G. KERN REPORTS TRANSFORMER IS REMOVED. HE DOUBLE WASHED STRUCUTRE WITH BIO-GEN 760, STRUCTURE IS CLEAN BUT MAKING WATER. TAG LEFT PENDING TRANSFORMER INSTALLATION.... E.VESCE 4/20/03=0400hrs CLEANUP COMPLETED DOULBED WASHED STRUCTURE USING BIO GEN 760 FOUND SUMP MAKING WATER UNABLE TO CEMENT. ALSO NO ENVIR TAG FOUND. "

Remarks: "1qt on 150 gallons water. con ed # 147399. crew responded to smoking transformer. no smoke or fire on arrival."

All Materials:

Site ID: 238683
Operable Unit ID: 863001
Operable Unit: 01
Material ID: 511757
Material Code: 0064A
Material Name: unknown material
Case No.: Not reported
Material FA: Other
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported